


3. Two cross step stile.  
Waymark post at roadside partially obscured, needs pruning saw to clear.

When approaching from Pen Y Turnpike Road stile cannot be seen, an extra waymark post would be helpful.

~~Stile step~~ required

2. Sleeper bridge, wire mesh was coming away causing trip hazard, have nailed down, but requires galvanised staples.

1. Two cross step stile, wobbly but usable. Possible hazard from barbed wire running forward from stile.



Penarth No.7 (Footpath)

03 November 2016

1:2,500



© Crown copyright and database rights  
2016 Ordnance Survey 100023424  
© Hawfrant y Goron a hawliau cronfa ddata  
2016 Arolwg Ordnans 100023424