

Access from road dangerous

5. No roadside post

No roadside post

4. Stile set back from road, but stepping onto road dangerous.

3. Waymark arrow on landowner's fence

Path encroached by undergrowth, Cleared during survey. May need clearing next year?

2. Partially fallen tree over path, does not block path, but potential hazard.


Good wide path

1. Waymark post

Penarth No.5 (Footpath) - BEWARE previous surveyor has noted that the access to this path from Pen-y-Turnpike Road is dangerous due to blind bend and fast traffic. Please access this path from the east end.

03 November 2016

1:1,250



© Crown copyright and database rights
2016 Ordnance Survey 100023424
© Hawlfraint y Goron a hawliau cronfa ddada
2016 Arolwg Ordans 100023424